



CT125 · HUNTER CUB

FOR CT125 HUNTER CUB
HAZARD / PASSING
FUNCTION BUILT-IN!



The hazard / passing functions that stock switch doesn't have at stock. Coupler-on to install. No wiring mods required!!

Kitaco Official YouTube Channel



How to install L handle switch assy with hazard is now on air!!

NO WIRING MODS REQUIRED!
COUPLER-ON!

L HANDLE SWITCH ASSY WITH HAZARD FUNCTION

CODE	PRICE
756-1470100 CLICK	¥ 17,000
● COUPLER-ON ● HAZARD SWITCH / PASSING FUNCTION BUILT-IN! ● LED WINKER RELAY INCLUDED	
APPLICATION	CT125 · HUNTER CUB (JA55)

* Hole making mods on handle bar required (paper pattern for the mods included)

DIMMER SWITCH

(HEADLIGHT HIGH/LOW SWITCH)

HAZARD SWITCH

★ NEWLY ADDED

PASSING

★ NEWLY ADDED


ATTENTION
Hazard lamp is not on while key is off

HORN SWITCH

WINKER SWITCH

(PUSH CANCEL)

CORRECTS SPEED METER ERRORS!
NO WIRING MODS REQUIRED
COUPLER-ON!!



Corrects speedometer error display for the vehicles which pick up speed pulse from sprockets.

SPEED PULSE CONVERT UNIT

CODE	PRICE
762-1470100 CLICK	¥ 10,000
● CORRECTS SPEED METER DISPLAY ERROR CAUSED BY SPROCKET TEETH CHANGE. ● CASE SIZE : 49 × 30 × 22mm	
APPLICATION	CT125 · HUNTER CUB (JA55)

* Not completely water-proof. Place it to somewhere that does not get wet.
* Precision screwdriver is required to open the lid/

EASY SETTING!

Open the lid, input front / rear sprocket teeth and tire size with the button.



SPEED PULSE CONVERT UNIT makes it possible to change sprocket teeth!

DRIVE SPROCKET (FRONT)

- 428 SIZE
- STOCK : 14T
- * Wide chain guide plate (see below) is required to use 15T/16T

TEETH	CODE	PRICE
14T	530-1444014	¥ 1,500
15T *	530-1444015	¥ 1,500
16T *	530-1444016	¥ 1,600

WIDE CHAIN GUIDE PLATE

- STEEL WITH BLACK



CODE	PRICE
683-1300400	¥ 1,300

DRIVEN SPROCKET (REAR)

- 428SIZE
- STEEL WITH BLACK
- STOCK : 39T

TEETH	CODE	PRICE
33T	535-1444033	¥ 2,000
34T	535-1444034	¥ 2,100
35T	535-1444035	¥ 2,200
36T	535-1444036	¥ 2,300
37T	535-1444037	¥ 2,400
NEW 38T	535-1444038	¥ 2,500
NEW 39T	535-1444039	¥ 2,600
NEW 40T	535-1444040	¥ 2,700

ATTENTION

Speed pulse convert unit is required when exchanging sprocket teeth numbers. Without it, ABS lamp blinks and ABS function does not work correctly.