MASTER CYLINDER TANK CAP

CODE

(BLUE) 500-9010010 (RED) 500-9010020 (BLACK) 500-9010050 (GOLD) 500-9010070

CAP O.D. : 38mm

[GENUINE PARTS NUMBER]

OMASTER CYLINDER CAP (HONDA GENUINE NAME)

HONDA: 43513-KWN-931 · 43513-KS6-701 YAMAHA: 2CR-25852-50 · 4FM-25852-00

SUZUKI: 69669-17K00 KAWASAKI: 43026-1070

Verification vehicle:

HONDA MONKEY 125 (rear) /K-CON MASTER CYLINDER CUP

• Thank you for purchasing Kitaco product. Read and understand the instruction before installing.

- trouble.
- We are not responsible for violation of law or damages and accidents caused by assembling mistake and improper setting.
- Please ask authorized mechanic for assembling and setting. Ask a specialist at specialty shop if you do not understand the role of the surrounding parts.
- Refer to the manufacturer service manual when installation.
- Bolts and nuts may get loosen by engine vibration. Make sure not to loosen any bolts and nuts before driving.
- *Metal/resin/alumite products get discolored/rust for ages as well as how to use. Please understand when using.


ATTENTION


- Brake fluid hurts paint. Protect by cloth, etc for installation.
- When overhaul master cylinder, make sure to bleed air, then refill fluid between UPPER and LOWER of the cup. Make sure that brake is working before riding.

ATTENTION ABOUT CAP TIGHTENING

About the master cylinder tank cap tightening, please follow the below.

- 1, (Temporarily tightening) Tighten tank cap clockwise by hand until resistance is felt. Make sure to install firmly to tank body (cup).
- 2, (Final tightening) Rotate the cap to 1/6 more while tank body to be fixed.





220629 M-T

〒 577-0015 3-8-13 NAGATA, HIGASHI-OSAKA, OSAKA, JAPAN